INCIDENT REPORT OF SEA TURTLE MORTALITY AND DREDGING ACTIVITY

Species: Caretta caretta

Date: 4/21/91

Time: 24 hour clock: ?

Geographic site: Brunswick Entrance Channel, GA

Location in channel: Stations 320 - 380

Location: Latitude _____ Longitude _____

Vessel name: Sugar Island

Type of dredging activity: Maintenance

Load #: 455

Sampling method: Lateral/skimmer overflow screens

Location specimen recovered: Port draghead

Draghead deflector _____ Yes ✓ No

Condition of deflector _____

Weather conditions: Clear; Wind, 10 knts SE; Seas - 3'; 72°F

Water temp: Surface _____ Column _____

Head width: ?

Plastron length _____

Carapace S.L. length _____

Carapace S.L. width _____

Carapace O.C. length _____

Carapace O.C. width _____

Condition of specimen: Missing head and left front flipper & portion of carapace.

Turtle tagged _____ Yes _____ No

Tag # _____ Tag Date _____

Comments/other _____

Observer's Name: Chris Slay