

ENDANGERED SPECIES OBSERVER PROGRAM

Project: BRUNSWICK CHANNEL

INCIDENT REPORT OF SEA TURTLE TAKE BY DREDGING ACTIVITY

Date 24 / MAR / 03 Time(24hr) 0300

Species of Turtle Taken CARETTA CARETTA

Dredging Site (channel, port, etc.) CHANNEL

Location of Take: Latitude 31° 7' Longitude 81° 21'

Vessel Name and Company MV EAGLE BEAN

Type of Dredging Activity HOPPER

Load # 1224 Times: Start 0127 End 0226 Dump 0307

Sampling Method (overflow, inflow, etc.) INFLOW

Samples Recovered From PORT DRAG HEAD

Condition of Screening OK

Draghead Deflector? Yes No

Condition of Deflector GOOD

Weather Conditions CLEAR, WIND NR 13KTS Tide +7.0

Water Temperature: Surface 62° F Column 61° F C or (circle one)

Condition of Specimen(s) Sampled OK - HEAD & FLIPPERS INTACT, 2/3 OF CARAPACE

MISSING, PLASTRON MOSTLY INTACT

Measurements--

Give estimate of entire carapace dimensions, as well as fragments sampled (in metric when possible, indicate if not):

Head Width 7"

Plastron Length 26.5" Width 24"

Carapace S. L. Length _____ S.L. Width _____

Carapace O.C. Length 31" O.C. Width 24"

Turtle Tagged? Yes _____ No Tag # _____ Tag Date / /

Comments _____

FLIPPER (L.F.) FROZEN FOR PRESERVATION

Observer's Name

Kimberly Keith Peters

CONTRACTOR'S QUALITY CONTROL REPORT		DATE: 3/24/2003	REPORT NO. 183
CONTRACT NUMBER AND NAME OF CONTRACTOR DACW21-02-C-0008 - BEAN STUYVESANT L.L.C.		DESCRIPTION AND LOCATION OF THE WORK: Brunswick Harbor Deepening St. Simons Sound and Entrance Channel Sta. 6+250 to Sta. 00+000, Sta. 00+00 to Sta. -56+500	
WEATHER CLASSIFICATION: CLASS A No Interruptions of any kind from weather conditions occurring this or previous shifts. CLASS B Weather occurred during this shift that caused a complete stoppage of all work. CLASS C Weather occurred during this shift that caused a partial stoppage of work. CLASS D Weather overhead excellent or suitable during shift. Work stopped due to results of previous adverse manner. CLASS E Weather overhead excellent or suitable during shift but work partially stopped due to previous adverse manner. OTHER Explain		CLASSIFICATION: <u>A</u> TEMPERATURE: MAX <u>74</u> MIN <u>52</u> PRECIPITATION: INCHES <u>0.00</u>	
CONTRACTORS/SUBCONTRACTORS AND AREA RESPONSIBILITY FOR WORK PERFORMED TODAY: (Attach list of items of equipment either idle or working as appropriate)			
A. Bean Stuyvesant, LLC - Prime Contractor			
B. Note: Personnel: Staff (3), Plowbarge (2), C.W. Byrne (2), Mob/Demob (6).			
C. Crewboats(1), Tug T. Crosby (4), Tug Champion (4). Total =22 Personnel.			
D. Eagle I = 24 Personnel			
E. Total personnel on at present =46.			
F.			
G.			
I. WORK PERFORMED TODAY: (Indicate location and description of work performed refer to work by prime and/or subcontractors by letter in table above)			
Hopper Dredge Eagle I: Dredging between sta. -40+000 and sta. -56+500.			
Eagle I Disposing in Cell G & H.			
Plowbarge working from Sta. -40+000 to Sta. -49+000.			
2. TYPE AND RESULTS OF INSPECTION: (Indicate whether: P-Preparatory, I-Initial, or F-Follow-up and include satisfactory work completed or deficiencies with action to be taken.): Follow up: Checked that safety equipment inspections up to date.			
3. TEST REQUIRED BY PLANS AND/OR SPECIFICATIONS PERFORMED AND RESULTS OF TEST: INCLUDED AS ATTACHMENTS None required.			
4. VERBAL INSTRUCTIONS RECEIVED: (List any instructions given by Government personnel on construction deficiencies, retesting required, etc., with action to be taken.) None given today.			

5. REMARKS: (Cover any conflicts in plans, specifications or instructions; acceptability of incoming materials; offsite surveillance activities; progress of work, delays, causes and extent thereof; days of no work for same. (If a Preparatory or Initial Phase Meeting was held, attach a copy of the checklist.)

Plowbarge. Working outside from sta. -40+000 to sta. -49+000.

Safety: Inspected outside fire stations.

Survey: Surveyed check sections behind dredge. Also surveyed disposal H.

Brunswick Channel Surveyed: Sta. -9+000 to -22+000
Sta. to

Note: Load 1224 took a turtle around 02:30. Also found a flipper in stbd. Chute aft in load 1227 around 08:00. Shut dredge down at Corps orders at 09:47 until further notice. Down thru 24:00.

Weather: Clear, Warm and sunny most of the day. Seas: 1-3 ft. Winds: NE-E 5-12 kts.

5. b. ENVIRONMENTAL QUALITY CONTROL

Environmental Quality Control Requirements are in place and have been checked? Yes Not Applicable

Have any endangered species been encountered? Yes No

(If Yes, attach required reports in accordance with Section ENVIRONMENTAL PROTECTION)

Shut down dredge after notifying Corps and environmental of apparently catching second turtle in one day.

5. c. VISITORS TO THE SITE (List the name of all official visitors to the site and who they represent.)

John and Clay are the Corps representatives onboard Eagle I.


Safety meeting held today? Yes No (If Yes, state the subject and report number of personnel in attendance)

Safety meeting subject: SEE ATTACHED SHEET

Number of Contractor personnel attending 0 Number of subcontractor personnel attending) 0

SEE ATTACHED SHEET.

Name of reporting QC Inspector: Robert Webb

SIGNATURE AND DATE: 

CONTRACTORS CERTIFICATION: I certify that the above report is complete and correct and that all material and equipment used, work performed and test conducted during this reporting period were in compliance with the contract.