Endangered Species Observer Program
LOAD DATA FORM

Project Name: MATAGORDA ENTRANCE USACE District: GALVESTON

Dredge Name: BAYPORT Dredge Firm: MANSON

Date 08 / 04 / 06 LOAD #: 55

Times (24hrs): Start 2148 End 2342 Dump 2348

Location, Lat/Long: N 28° 23.60 W 96° 17.56

Condition of screening : Port good Starboard good Overflow good

Number of dragheads in use: 2 Type of dragheads used: 1 HC Size of dragheads: _____
Draghead deflector? YES ✓ NO ___ Condition of deflector: good

Type of material dredged: SILT
Weather conditions: mostly clear

Tidal stage (CIRCLE ONE): Slack Rising High Falling Low Unknown

Beaufort Sea States (Enter BSS 1-8) 2 Wave Height: 1-2 ft

Wind (speed & direction): SE 5-10 AIR TEMP: 88 °C/(F) (°F = 9/5 (°C) + 32; °C = 5/9 (°F - 32))

WATER TEMP: Surface 29 (°C)/°F Column (mid-depth) — °C / °F Bottom — °C / °F

SCREEN TYPE

X	Inflow screening:	None	25%	50%	75%	(100%)
X	Overflow screening:	None	25%	50%	75%	(100%)
	Other screening:	None	25%	50%	75%	100%

PORT SCREEN CONTENTS: debris (wood, rope, trash)

STARBOARD SCREEN CONTENTS: debris (wood, rope, trash)

Estimate number entrained on this load for the following:

Sturgeon (any species) ___
Shark (any species) ∅
Horseshoe crab ___
Blue crab 2

TURTLE OR TURTLE PARTS PRESENT THIS LOAD: YES ✓ NO ___
SPECIES OF TURTLE TAKE: Unknown Loggerhead Green (Kemp's ridley) Hawksbill Leatherback

Comments: Carapace carcass found on aft weir
unclogged weir (aft)
Section 3

Number observers used/24hrs: 2 % Monitoring/24 hrs: None 25% 50% 75% (100%)

Observer's Name: Becky Cline Observer firm COASTWISE CONSULTING